



CALUMPIT WATER DISTRICT

Bids and Awards Committee
M. Serrano St., Corazon Calumpit, Bulacan
Tel No.: (044) 675-1453 / 913-0079
Email address: calumpitwd@yahoo.com

BAC RESOLUTION NO. 2018-036

Re: Deep Well Video Inspection (Camera Logging) of Caniogan PS and Northville IX PS
(Please see attached purchase request for item description)

WHEREAS, the Bids and Awards Committee is hereby instructed to act upon the CWD with Job Request No. 2018-02-023; Deep Well Video Inspection (Camera Logging) of Caniogan PS and Northville IX PS;


WHEREAS, the members of the BAC agreed to adopt Section 53.9, Article XVI of RA 9184, which states the use of Small Value Procurement, a method of procurement of Goods, Infrastructure and Consulting Services where the amount involved does not exceed the thresholds prescribed in Annex "H" of this IRR: Provided, That in case of Goods, the procurement does not fall under shopping in Section 52 of this IRR.^(a)


The BAC shall prepare and send the RFQs/RFPs to at least three (3) suppliers, contractors or consultants of known qualifications. This, notwithstanding, those who responded through any of the required postings shall be allowed to participate. Receipt of at least one (1) quotation is sufficient to proceed with the evaluation thereof.


NOW THEREFORE, We, the members of Bids and Awards Committee, hereby RESOLVE as it is hereby RESOLVED;

1. To recommend the use of Small Value Procurement for Job Request No. 2018-02-023.
2. To recommend for approval by the General Manager of the Calumpit Water District the foregoing findings;


RESOLVED, at the CWD Office, Corazon, Calumpit, Bulacan, this 20th of February 2018.


EDILBERTO P. SANTOS
BAC Vice Chairman



MARICAR D. JOAQUIN
BAC Member




EMELY E. ECHEVARRIA
BAC Chairman


ANTONIO M. CRUZ
BAC Member


RONALDO D.C. TANTOCO
BAC Member


ESPERANZA L. CORTES
BAC Member


Engr. RONNIE B. LARGADO
General Manager, Head of the Procuring Entity
Approved on 02/20/18

Office/Section : Engineering & Operations Dept.		PR No.: 2013-02-022 Responsibility Center Code :		Date: 14-Feb-18	
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
	lot	Deep Well Video Inspection (Camera Logging)	2	50,000.00	100,000.00
		Estimated Cost			100,000.00
Purpose: For inspection of Catiogan and Northville IX Pumping Stations' deepwell current situation.					
Requested by:		Approved by:			
Signature : 		Signature :  02/15			
Printed Name : EDILBERTO P. SANTOS		Engr. RONNIE B. LARGADO			
Designation : Department Manager, EOD		General Manager			

Amor
2/19/18
1.45