

REPUBLIC OF THE PHILIPPINES CALUMPIT WATER DISTRICT

Bids and Awards Committee

M. Serrano St., Corazon Calumpit, Bulacan Tel No.: (044) 675-1453 / 913-0079 Email address: calumpitwd@yahoo.com

BAC RESOLUTION NO. 2020-241

Supply of Labor & Materials for the Repair of Submersible Pump & Motor (Calizon PS)

WHEREAS, the Bids and Awards Committee is hereby instructed to act upon the CWD with Purchase Request No. 2020-10-032; Supply of Labor & Materials for the Repair of Submersible Pump & Motor;

WHEREAS, the members of the BAC agreed to adopt Section 53.9, Article XVI of RA 9184, which states the use of <u>Small Value Procurement</u>, a method of procurement of Goods, Infrastructure and Consulting Services where the amount involved does not exceed the thresholds prescribed in Annex "H" of this IRR: Provided, That in case of Goods, the procurement does not fall under shopping in Section 52 of this IRR.(a)

The BAC shall prepare and send the RFQs/RFPs to at least three (3) suppliers, contractors or consultants of known qualifications. This, notwithstanding, those who responded through any of the required postings shall be allowed to participate. Receipt of at least one (1) quotation is sufficient to proceed with the evaluation thereof.

NOW THEREFORE, We, the members of Bids and Awards Committee, hereby RESOLVE as it is hereby RESOLVED;

- 1. To recommend the use of Small Value Procurement for Purchase Request No. 2020-10-032.
- To recommend for approval by the General Manager of the Calumpit Water District the foregoing findings;

RESOLVED, at the CWD Office, Corazon, Calumpit, Bulacan, this 5th of November 2020.

EMELY E. ECHEVARRIA

BAC Chairman

ESPERANZA L. CORTEZ

BAC Vice Chairman

EDILBERTO P. SANTOS

BAC Member

Engr. RONNIE B. LARGADO

General Manager, Head of the Procuring Entity

Approved on

//amc.bacsecretariat.2020

RONALDO DC. TANTOCO

BAC Member

BENIOS. TORRES

BAG Member

PURCHASE REQUEST

Entity Name: CALUMPIT WATER DISTRICT

Fund Cluster:

Enngg & Operations		PR No.: 2020- 10-027 Responsibility Center Code:		Date:	Oct. 22, 2020
Dept.		Tresponsibility Center Code .			
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
		For Repair of submersible Pump and Motor :			
		FRANKLIN Motor	1	22,000.00	22,000.00
		Serial No. 15J19-24-080378			
		Model: 2396018521			
		HP/KW Rating: 50HP/37KW			
	unit	PLEUGER Pump	1	40,000.00	40,000.00
		Model: PN 82-5			
		See attached Evaluation Form			
		Estimated Total Cost			62,000.00
Purpose: For repair of pump and motor from Calizon PS to determine the cost of repair.					
	Reques	quested by:			
Signature :				3/2) k	
Printed Name :		ED BERTOP. SANTOS	En	gr. RONNIE B.	LARGADO
Designation:	Department Manager, EOD	General Manager			