

BAC RESOLUTION NO. 2021-197

Supply, Delivery Installation, Testing & Commissioning of 1 Lot CCTV Camera for Calizon Pumping Station

(CCTV camera damaged by lightning)

HEREAS, the Bids and Awards Committee is hereby instructed to act upon the CWD with Purchase Request No. 2021-09-005 ; **Supply, Delivery Installation, Testing & Commissioning of 1 Lot CCTV Camera for Calizon Pumping Station ;**


HEREAS, the members of the BAC agreed to adopt Section 52, Article XVI of RA 9184, which states the use of Shopping, a method of procurement of goods whereby the Procuring Entity simply requests for the submission of price quotations for readily available off-the-shelf goods or ordinary/regular equipment to be procured directly from suppliers of known qualifications. This method of procurement shall be employed in any of the following cases:


- a) When there is an unforeseen contingency requiring immediate purchase: *Provided, however,* that the amount shall not exceed the thresholds prescribed in Annex "H" of this IRR.
- b) Procurement of ordinary or regular office supplies and equipment not available in the Procurement Service involving an amount not exceeding the thresholds prescribed in Annex "H" of this IRR.


NOW THEREFORE, We, the members of Bids and Awards Committee, hereby RESOLVE as it is hereby RESOLVED;


1. To recommend the use of Shopping for Purchase Request No. 2021-09-005 ;
2. To recommend for approval by the General Manager of the Calumpit Water District the foregoing finding;

RESOLVED, at the CWD Office, Corazon, Calumpit, Bulacan, this 16th day of September 2021.


EMELY E. ECHEVARRIA
BAC Chairman


ESPERANZA L. CORTEZ
BAC Vice Chairman


EDILBERTO P. SANTOS
BAC Member


RONALDO D.C. TANTOCO
BAC Member


BENJOS. TORRES
BAC Member

PURCHASE REQUEST

PIT WATER DISTRICT


Fund Cluster:


PR No.: 2021-09-005 Date: September

pt. Responsibility Center Code :

| Unit | Item Description | Quantity | Unit Cost |
|------|--|----------|------------|
| L.S. | Supply, Delivery, Installation, Testing and Commissioning of One (1) Lot CCTV Camera's damaged by lightning at Calizon Pumping Station | 1 | 105,690.00 |
| | Parts to be replaced: | | |
| | 1 pc. Hikvision Bullet Type | | |
| | 1 pc. Hikvision Dome Type | | |
| | 1 pc. Radio Antenna | | |
| | 1 pc. Hikvision POE Switch | | |
| | Additional Accessories: | | |
| | 1 set Lightning Arrester | | |
| | 1 pc. UPS 650 VA | | |
| | Works to be done: | | |
| | 1. Disassembled existing CCTV cameras | | |
| | 2. Disassembled existing radio antenna | | |
| | 3. Installation of new CCTV cameras | | |
| | 4. Installation of new radio antenna | | |
| | 5. Re-wiring | | |
| | 6. Installation of lightning arrester | | |
| | 7. Testing and commissioning | | |
| | Grand Total (VAT Inclusive) | | |

Purpose: **To restore the operation of CCTV system at Calizon Pumping Station.**

Requested by: 
EDILBERTO P. SANTOS
 EOD Department Manager

Approved by: 
Engr. RONNIE B.
 General Ma