## CALUMPIT WATER DISTRICT Bids and Awards Committee

M. Serrano St., Corazon Calumpit, Bulacan Tel No.: (044) 675-1453 / 913-0079 Email address: calumpitwd@yahoo.com

## **BAC RESOLUTION NO. 2021-216**

## Provision of Deepwell Video Inspection (Camera Logging) at Northville IX and Calizon Pumping Station

WHEREAS, the Bids and Awards Committee is hereby instructed to act upon the CWD with Purchase Request No. 2021-10-014; Provision of Deepwell Video Inspection (Camera Logging) at Northville IX and Calizon Pumping Station;

WHEREAS, the members of the BAC agreed to adopt Section 53.9, Article XVI of RA 9184, which states the use of <u>Small Value Procurement</u>, a method of procurement of Goods, Infrastructure and Consulting Services where the amount involved does not exceed the thresholds prescribed in Annex "H" of this IRR: Provided, That in case of Goods, the procurement does not fall under shopping in Section 52 of this IRR.<sub>(a)</sub>

The BAC shall prepare and send the RFQs/RFPs to at least three (3) suppliers, contractors or consultants of known qualifications. This, notwithstanding, those who responded through any of the required postings shall be allowed to participate. Receipt of at least one (1) quotation is sufficient to proceed with the evaluation thereof.

NOW THEREFORE, We, the members of Bids and Awards Committee, hereby RESOLVE as it is hereby RESOLVED;

- 1. To recommend the use of Small Value Procurement for Purchase Request No. 2021-10-014;
- 2. To recommend for approval by the General Manager of the Calumpit Water District the foregoing findings;

RESOLVED, at the CWD Office, Corazon, Calumpit, Bulacan, this 18th day of October 2021.

ESPERANZA L. CORTEZ

BAC Vice Chairman

EDILBERTO P. SANTOS

BAC Member

BAC Chairman

RONALDO DC. TANTOCO

BAC Member

BENJO S. TORRES

BAC Member

Engr. RONNIEB. LARGADO

General Manager, Head of the Procuring Entity

Approved on 0 - 18 - 11

## JOB REQUEST

Entity Name: CALUMPIT WATER DISTRICT

Fund Cluster:

| Enngg & Operations   |       | PR No.: 2021-10-014  Responsibility Center Code:                            |                 | Date:         | Oct. 14, 2021 |
|--|-------|---|-----------------|---------------|---------------|
| Stock/ Property No.  | Unit  | Item Description  | Quantity        | Unit Cost     | Total Cost    |
| Property No.   |       |   |                 |               |               |
|  | lot   | Deep Well Video Inspection (Camera Logging) of Northville IX and Calizon PS | 2               | 60,000.00     | 120,000.00    |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       |   |                 |               |               |
|  |       | Estimated Cost  |                 |               | 120,000.00    |
|  |       |   |                 |               |               |
| Purpose: For inspection and evaluation of the current situation of deep wells . Included in APP Item No. 2 |       |   |                 |               |               |
| 1 of moposition and ovalidation of the ballott of deep work . Holdada in 7th 1 from No. 2                  |       |   |                 |               |               |
|  | Reque | sted by:  | Approved by:    |               |               |
| Signature : Printed Name :   |       | EDITE SANTOS  | + or Fr         | gr. RONNIE B. | LARGADO 4     |
| Designation :  |       | Department Manager, EOD   | General Manager |               |               |